




Methods of mounting RIDGE VENTILATION




1. Before the installation of roofing do the slots (two of 2.5 cm or a 5 cm). Slots must end not less than 30 cm from the edge of ridge..




2. Start laying the first strip RIDGE VENTILATION 10 cm from the edge of your roof.




3. Pay attention to the place where the need to screw bolts and drive nails with roofing material.



4. Connect the ends of profiles with each other. Panels strengthen screws up less than 6 cm.



5. Cover profile RIDGE VENTILATION roofing materials with nails on the specified line Nail line.



6. Roofing place for technology manufacturer of roofing materials.

1 item profile provides 5 m² roof ventilation.
Calculation is carried out under the condition that the roof is insulated to climate zone.